

EMC31010-MANUFACTURING TECHNOLOGY-I
CENTRAL POLYTECHNIC COLLEGE, THARAMANI – 600113.

(An Autonomous Institution)

**DEPARTMENT OF MECHANICAL ENGINEERING
(CAD)**



QUESTION BANK

**EMC31010 – MANUFACTURING TECHNOLOGY-I
(E – SCHEME)**

U.NO Q NO

QUESTIONS

- 1 1 Which material is most commonly used for patterns in short-run production?
 (a) Wood (b) Steel
 (c) Graphite (d) Ceramic
Ans:Graphite
- 1 2 The parameter primarily affecting arc penetration is
 (a) Welding current (b) Arc voltage
 (c) Travel angle (d) Humidity
Ans:Welding current
- 1 3 TIG electrodes are commonly alloyed with
 (a) Thoria or ceria (b) Zinc
 (c) Lead (d) Magnesium
Ans:Thoria or ceria
- 1 4 Resistance seam welding produces
 (a) A continuous weld (b) Intermittent nuggets only
 (c) Brazed joint (d) No heat affected zone
Ans:Intermittent nuggets only
- 1 5 Backhand welding technique means the torch is inclined
 (a) Opposite to the direction of travel (b) Same as travel
 (c) Perpendicular only (d) Random
Ans:Opposite to the direction of travel
- 1 6 A major advantage of MIG over SMAW is
 (a) Higher deposition rate (b) Lower equipment cost
 (c) No shielding needed (d) Immutable polarity
Ans:Higher deposition rate
- 1 7 Arc length in SMAW is roughly equal to
 (a) Diameter of the electrode core (b) Twice the electrode diameter
 (c) Half the electrode diameter (d) Irrelevant
Ans:Diameter of the electrode core
- 1 8 Post-weld heat treatment can be used to
 (a) Relieve residual stresses (b) Increase hardenability of all steels
 (c) Remove alloying elements (d) Create porosity
Ans:Relieve residual stresses
- 1 9 The function of flux coating in SMAW is to
 (a) Stabilize arc and provide shielding (b) Increase current
 (c) Cool the weld pool (d) Act only as filler
Ans:Stabilize arc and provide shielding
- 1 10 Which personal protective item is mandatory for arc welding?
 (a) Face shield with proper filter (b) Ear plugs only
 (c) Rubber gloves only (d) Respirator only
Ans:Face shield with proper filter

U.NO	Q NO	QUESTIONS	
1	11	Arc blow is more common with (a) DC welding (c) Gas welding Ans:DC welding	(b) AC welding (d) Laser welding
1	12	Which current type is preferred for welding aluminium with TIG? (a) AC (c) DCEP Ans:AC	(b) DCEN (d) Pulsed DC only
1	13	Preheating is recommended to (a) Reduce cooling rate and cracking (c) Increase hardness only Ans:Reduce cooling rate and cracking	(b) Increase spatter (d) Make arc starting easier only
1	14	Undercut is a defect that appears as (a) Groove along weld toe (c) Crater at weld end Ans:Groove along weld toe	(b) Excess metal reinforcement (d) Overlap of metal
1	15	Porosity in welds is caused mainly by (a) Entrapped gas (c) Too small electrode Ans:Entrapped gas	(b) Excess heat input (d) High current only
1	16	Electrode classification E6013 indicates (a) Tensile strength 60 ksi, position 1, flux type 3 (c) Stainless electrode Ans:Tensile strength 60 ksi, position 1, flux type 3	(b) Tensile 80 ksi, position 3, flux 1 (d) Aluminium electrode
1	17	Weld symbol for a fillet weld is (a) A right-angled triangle (c) A square Ans:A right-angled triangle	(b) A circle (d) A hexagon
1	18	Butt, lap and tee are (a) Joint types (c) Electrode types Ans:Joint types	(b) Weld symbols (d) Defects
1	19	Shell moulding uses resin-coated sand and provides (a) Good surface finish & accuracy (c) No cores possible Ans:Good surface finish & accuracy	(b) Very low strength (d) Only very large parts
1	20	Hydrogen cracking in welds is promoted by (a) High restraint and diffusible hydrogen (c) Dry electrodes Ans:High restraint and diffusible hydrogen	(b) High preheat (d) Austenitic filler

U.NO	Q NO	QUESTIONS
1	21	The term fettling in foundry refers to (a) Removing gates, risers and cleaning (b) Pouring metal (c) Mould ram-up (d) Pattern making Ans:Removing gates, risers and cleaning
1	22	Rapping allowance is given because (a) Pattern is shaken before withdrawal (b) Metal shrinks (c) Machining needed (d) Cores swell Ans:Pattern is shaken before withdrawal
1	23	In sand casting, a typical vent is provided to (a) Allow gases to escape (b) Feed metal (c) Support cores (d) Locate gating Ans:Allow gases to escape
1	24	The function of a choke in gating is to (a) Regulate flow rate (b) Collect slag (c) Feed shrinkage (d) Vent gases Ans:Regulate flow rate
1	25	For stainless steels, to avoid sensitization, welding practice often uses (a) Low heat input and stabilized grades (b) High heat input and slow cooling (c) No shielding gas (d) Copper electrodes Ans:Low heat input and stabilized grades
1	26	Full mould (lost foam) casting uses patterns made of (a) Polystyrene (foam) (b) Wax (c) Sandstone (d) Plaster of Paris Ans:Polystyrene (foam)
1	27	The heat-affected zone (HAZ) is the region (a) Not melted but microstructurally changed (b) Completely melted and solidified (c) Unaffected base metal (d) Only flux layer Ans:Not melted but microstructurally changed
1	28	In GMAW with CO ₂ shielding, arc is usually (a) More penetrating but spattery (b) Softer with less penetration (c) Not stable (d) Cold Ans:Not stable
1	29	The most suitable flame for welding mild steel is (a) Neutral flame (b) Oxidizing flame (c) Carburizing flame (d) No flame Ans:Neutral flame
1	30	The collapsibility of moulding sand is desirable to (a) Avoid hot tears during contraction (b) Increase green strength (c) Reduce permeability (d) Increase hardness Ans:Avoid hot tears during contraction

U.NO	Q NO	QUESTIONS	
1	31	Inclusion defects are minimized by using (a) Proper gating and filters (c) Low riser	(b) Slow superheat (d) No slag removal
		Ans:Proper gating and filters	
1	32	Exothermic sleeves around risers are used to (a) Keep the riser hot for feeding (c) Reduce permeability	(b) Cool the riser (d) Increase gas evolution
		Ans:Keep the riser hot for feeding	
1	33	Chvorinov's rule relates solidification time to (a) Volume-to-surface area ratio (c) Sand grain size only	(b) Pouring temperature only (d) Riser height only
		Ans:Volume-to-surface area ratio	
1	34	Welding position '1G' denotes (a) Flat position for groove weld (c) Vertical up	(b) Horizontal fillet (d) Overhead
		Ans:Flat position for groove weld	
1	35	In TIG welding, filler metal is (a) Added separately as a rod (c) Not required	(b) Always part of the tungsten (d) Automatically fed wire only
		Ans:Added separately as a rod	
1	36	In gas welding, backfire is a condition when (a) Flame momentarily extinguishes with a pop (c) Gas runs out	(b) Hose bursts (d) Regulator freezes
		Ans:Flame momentarily extinguishes with a pop	
1	37	The neutral oxy-acetylene flame has an approximate temperature of (a) About 3200°C (c) About 4500°C	(b) About 1800°C (d) About 900°C
		Ans:About 3200°C	
1	38	A typical binder used in green sand is (a) Bentonite clay (c) Polyester	(b) Epoxy resin (d) Sodium silicate
		Ans:Bentonite clay	
1	39	Facing sand is applied to (a) Improve surface finish near the pattern (c) Reduce mould hardness	(b) Increase permeability throughout (d) Increase moisture uniformly
		Ans:Improve surface finish near the pattern	
1	40	Core prints on a pattern are used to (a) Support the core in the mould (c) Feed the casting	(b) Vent the mould (d) Locate risers
		Ans:Support the core in the mould	

U.NO	Q NO	QUESTIONS
1	41	<p>Dry sand moulds are preferred when</p> <p>(a) High dimensional accuracy is required</p> <p>(b) Very quick production is needed</p> <p>(c) Low pouring temperature metals are used</p> <p>(d) Cores are unnecessary</p> <p>Ans:Very quick production is needed</p>
1	42	<p>Green sand moulding is performed with sand that is</p> <p>(a) Moist and unbaked</p> <p>(b) Dry and baked</p> <p>(c) Oiled and baked</p> <p>(d) Sand mixed with resin</p> <p>Ans:Moist and unbaked</p>
1	43	<p>High refractoriness in moulding sand resists</p> <p>(a) Fusing at high temperature</p> <p>(b) Moisture pickup</p> <p>(c) Gas evolution</p> <p>(d) Metal penetration</p> <p>Ans:Fusing at high temperature</p>
1	44	<p>Excessive moisture in green sand mainly reduces</p> <p>(a) Permeability</p> <p>(b) Refractoriness</p> <p>(c) Collapsibility</p> <p>(d) Green strength</p> <p>Ans:Permeability</p>
1	45	<p>The property of sand that allows gases to escape during pouring is</p> <p>(a) Permeability</p> <p>(b) Cohesiveness</p> <p>(c) Refractoriness</p> <p>(d) Collapsibility</p> <p>Ans:Permeability</p>
1	46	<p>The allowance provided to counter metal contraction during solidification is</p> <p>(a) Shrinkage allowance</p> <p>(b) Draft allowance</p> <p>(c) Distortion allowance</p> <p>(d) Rapping allowance</p> <p>Ans:Distortion allowance</p>
1	47	<p>Match-plate patterns are commonly made from</p> <p>(a) Aluminium</p> <p>(b) Cast iron</p> <p>(c) Copper</p> <p>(d) Lead</p> <p>Ans:Aluminium</p>
1	48	<p>Which pattern type is best for very large castings made in segments?</p> <p>(a) Skeleton pattern</p> <p>(b) Match-plate pattern</p> <p>(c) Cope-and-drag pattern</p> <p>(d) Loose piece pattern</p> <p>Ans:Skeleton pattern</p>
1	49	<p>Draft allowance on a pattern is provided to</p> <p>(a) Ease withdrawal from the sand</p> <p>(b) Compensate shrinkage</p> <p>(c) Allow machining later</p> <p>(d) Increase surface finish</p> <p>Ans:Ease withdrawal from the sand</p>
1	50	<p>Which of the following is NOT a pattern allowance?</p> <p>(a) Cooling allowance</p> <p>(b) Draft allowance</p> <p>(c) Shrinkage allowance</p> <p>(d) Machining allowance</p> <p>Ans:Cooling allowance</p>

U.NO	Q NO	QUESTIONS
2	1	Shear fracture surface in blanking ideally shows (a) Burnish zone + fracture zone (b) Only fracture zone (c) Only burnish zone (d) No zones Ans:Burnish zone + fracture zone
2	2	A cam-driven press is often used for (a) High-speed light stampings (b) Large hot forgings (c) Slow heavy draws (d) Open-die work Ans:High-speed light stampings
2	3	In hot working, strain rate sensitivity (a) Improves formability (b) Decreases ductility (c) Always causes necking (d) Removes oxide Ans:Improves formability
2	4	Roll forging improves (a) Directional grain flow (b) Porosity (c) Segregation (d) Cracking tendency Ans:Directional grain flow
2	5	Piercing punch failure is minimized by (a) Proper clearance and sharpness (b) Removing shear (c) Using soft punch material (d) Dry operation always Ans:Proper clearance and sharpness
2	6	Channel bending forms (a) U-shaped sections (b) Circular flanges (c) Beads (d) Embossed logos Ans:Circular flanges
2	7	Press working safety requires (a) Two-hand controls or guards (b) Open unguarded dies (c) Overriding interlocks (d) Removing light curtains Ans:Two-hand controls or guards
2	8	Die setters adjust (a) Alignment and shut height (b) Hardness of sheet (c) Melting temperature (d) Electrical power Ans:Alignment and shut height
2	9	Roll forging is most suitable for (a) Preforms before closed-die forging (b) Final finishing of gears (c) Sheet metal cups (d) Wire drawing Ans:Preforms before closed-die forging
2	10	A bolster plate in a press (a) Supports and locates the die set (b) Holds the punch (c) Feeds the strip (d) Lubricates the sheet Ans:Supports and locates the die set

U.NO	Q NO	QUESTIONS
2	11	Transfer die operations move (a) Workpiece from station to station between strokes (b) Strip remains stationary (c) Single hit operation (d) Only manual loading Ans:Workpiece from station to station between strokes
2	12	Parting off in press work means (a) Separating the finished part from strip (b) Piercing a hole (c) Embossing (d) Coining Ans:Separating the finished part from strip
2	13	Trimming is used to (a) Remove excess material after forming (b) Increase thickness (c) Add features (d) Reduce hardness Ans:Remove excess material after forming
2	14	Progressive die pitch is (a) Advance of strip per stroke (b) Die clearance (c) Punch radius (d) Shut height Ans:Advance of strip per stroke
2	15	Swelling at cup flange indicates (a) Insufficient blank-holder pressure (b) Excessive lubrication (c) Correct drawing (d) Too small punch radius Ans:Insufficient blank-holder pressure
2	16	Die life increases with (a) Proper lubrication & alignment (b) Excess tonnage (c) Soft die blocks (d) No stripping plate Ans:Proper lubrication & alignment
2	17	Bend allowance accounts for (a) Material elongation in the bend (b) Die clearance (c) Springback (d) Blank thickness change only Ans:Material elongation in the bend
2	18	Press tonnage required for blanking increases with (a) Perimeter and thickness (b) Blank area only (c) Die hardness only (d) Lubricant type only Ans:Perimeter and thickness
2	19	Angle bending forms (a) A V or L shape (b) A closed ring (c) A helical coil (d) A dome Ans:A V or L shape
2	20	Smith forging is usually performed using: (a) Power press (b) Hand hammer (c) Drop hammer (d) Hydraulic press Ans:Hand hammer

U.NO	Q.NO	QUESTIONS	
2	21	Drawing operation in press work is used to: (a) Bend the sheet (c) Produce cup-like shapes Ans:Produce cup-like shapes	(b) Cut the sheet (d) Join sheets
2	22	Which die type performs multiple operations in sequence along the strip? (a) Progressive die (c) Transfer die Ans:Progressive die	(b) Compound die (d) Coining die
2	23	Roll forging operation feed is measured in (a) Reduction per pass (c) Amps Ans:Degrees	(b) Strokes per minute (d) Degrees
2	24	Piercing vs blanking difference is that (a) Piercing removes scrap; blank is product (c) Both same Ans:Piercing removes scrap; blank is product	(b) Piercing gives product; blank is scrap (d) Blanking always after piercing
2	25	Hydraulic presses are preferred for (a) Long stroke and controllable force (c) Energy storage Ans:Long stroke and controllable force	(b) Very high speed (d) Impact blows
2	26	Annealing after cold work is used to (a) Restore ductility (c) Decrease grain growth always Ans:Restore ductility	(b) Increase work hardening (d) Create martensite
2	27	Neutral axis in bending shifts (a) Toward the inside radius (c) Remains centered Ans:Toward the inside radius	(b) Toward the outside (d) Randomly
2	28	Shut height of a press is (a) Distance between ram and bed at BDC (c) Stroke length Ans:Distance between ram and bed at BDC	(b) Height of die block (d) Press opening at TDC
2	29	Fine blanking requires (a) V-ring and high pressure pads (c) Hot sheet Ans:V-ring and high pressure pads	(b) Large clearance (d) No support plate
2	30	Ironing in cans manufacturing (a) Reduces wall thickness after drawing (c) Adds holes Ans:Reduces wall thickness after drawing	(b) Increases bottom thickness (d) Makes embossing

U.NO	Q NO	QUESTIONS	
2	31	Wrinkle in flange during drawing indicates (a) Low blank holder force or friction (c) Too high drawing ratio only Ans:Low blank holder force or friction	(b) Excess clearance (d) Perfect forming
2	32	Cupping test is used to assess (a) Sheet metal formability (c) Hardness only Ans:Sheet metal formability	(b) Tensile strength only (d) Impact toughness
2	33	Coining pressure compared to bending (a) Is much higher (c) Is lower Ans:Is much higher	(b) Is similar (d) Is negligible
2	34	Fine blanking achieves (a) Smooth, nearly shear-free edges (c) Only rough cuts Ans:Smooth, nearly shear-free edges	(b) Large burrs (d) Hot shearing
2	35	Deep drawing is characterized by (a) Cup height greater than diameter of punch radii control (c) Only hot forming Ans:No blank holder needed	(b) Very small punch travel (d) No blank holder needed
2	36	Isothermal forging maintains (a) Workpiece and die at similar temperature (c) Dies at cryogenic temperature Ans:Workpiece and die at similar temperature	(b) Workpiece at room temperature (d) Only vacuum
2	37	Hot working is typically performed (a) Above recrystallization temperature (c) At cryogenic temperature Ans:Above recrystallization temperature	(b) Below room temperature (d) Just below melting point
2	38	A key advantage of hot working over cold working is (a) Elimination of work hardening (c) Tighter tolerances Ans:Elimination of work hardening	(b) Better surface finish (d) No oxidation
2	39	Press brake is commonly used for (a) Bending sheet metal (c) Upsetting Ans:Bending sheet metal	(b) Blanking (d) Swaging wire
2	40	Smith forging is also known as (a) Hand forging (c) Upset forging Ans:Hand forging	(b) Drop forging (d) Roll forging

U.NO	Q NO	QUESTIONS	
2	41	Drop forging uses (a) A falling hammer and dies (c) Rotating rolls Ans:A falling hammer and dies	(b) Hydraulic extrusion (d) Explosive forming
2	42	Upset forging primarily increases (a) Cross-sectional area (c) Porosity Ans:Cross-sectional area	(b) Length (d) Grain size only
2	43	Roll forging reduces (a) Cross-section through rolling dies (c) Length to zero Ans:Cross-section through rolling dies	(b) Temperature to room temperature (d) Ductility
2	44	In hot rolling, scale formation is mainly due to (a) Oxidation of the surface (c) Carbide precipitation Ans:Oxidation of the surface	(b) Work hardening (d) Hydrogen embrittlement
2	45	Flash is a characteristic of (a) Impression die forging (c) Press braking Ans:Impression die forging	(b) Open die forging (d) Wire drawing
2	46	Press capacity is commonly rated in (a) Tonnage (c) Litres Ans:Tonnage	(b) Watts (d) Amperes
2	47	In a hydraulic press, force is generated by (a) Fluid pressure on a ram (c) Elastic spring Ans:Fluid pressure on a ram	(b) Kinetic energy of a flywheel (d) Centrifugal force
2	48	Blanking operation produces (a) A part from sheet (the blank) (c) A beveled edge Ans:A part from sheet (the blank)	(b) A hole in the sheet (d) A fold
2	49	Piercing operation produces (a) A hole in the sheet (c) A rib Ans:A hole in the sheet	(b) A finished blank (d) A flange
2	50	Clearance in shearing depends primarily on (a) Sheet thickness (c) Die material Ans:Sheet thickness	(b) Ram speed (d) Lubricant type

U.NO	Q NO	QUESTIONS	
3	1	Full annealing produces (a) Coarse pearlite with maximum softness (c) Martensite Ans:Coarse pearlite with maximum softness	(b) Fine bainite with high strength (d) Austenite at room temp
3	2	Case depth in carburizing depends on (a) Time and temperature (c) Only quench medium Ans:Time and temperature	(b) Only carbon content of steel (d) Only surface finish
3	3	Induction hardening is most effective for (a) Medium carbon steels (c) Aluminium Ans:Medium carbon steels	(b) Low carbon steels without carburizing (d) Copper
3	4	Carburizing is followed typically by (a) Quench and temper (c) No further treatment Ans:No further treatment	(b) Anneal and slow cool only (d) Austemper only
3	5	Tempered martensite is (a) Stronger than pearlite but less brittle than martensite (c) Same as ferrite Ans:Stronger than pearlite but less brittle than martensite	(b) Brittler than untempered (d) Austenite
3	6	Lubricant in PM helps to (a) Reduce die wall friction during compaction (c) React chemically to harden Ans:Reduce die wall friction during compaction	(b) Increase porosity after sintering (d) Increase oxide content
3	7	Powder size is often measured by (a) Sieve analysis (c) Rockwell test Ans:Sieve analysis	(b) Charpy impact (d) Ultrasonic C-scan
3	8	Hot isostatic pressing (HIP) combines (a) High temperature and high gas pressure (c) Vibration and cooling Ans:High temperature and high gas pressure	(b) Low pressure and low temperature (d) Rolling and pressing
3	9	Cold isostatic pressing applies pressure (a) Hydrostatically in all directions (c) Thermally Ans:Hydrostatically in all directions	(b) Only uniaxially (d) By hammering
3	10	Sintering atmosphere of hydrogen is (a) Reducing (c) Inert only Ans:Reducing	(b) Oxidizing (d) Carburizing

U.NO	Q NO	QUESTIONS
3	11	Residual austenite is reduced by (a) Cold treatment (sub-zero) (c) No quench Ans: Cold treatment (sub-zero)
		(b) Higher austenitizing (d) Slower cooling through Ms
3	12	Sintering neck growth improves (a) Strength and density (c) Oxide inclusions Ans: Strength and density
		(b) Porosity only (d) Grain size only
3	13	Quench cracks are minimized by (a) Proper preheat and tempering (c) Very fast water quench always Ans: Proper preheat and tempering
		(b) No tempering (d) Overheating
3	14	Green sand moulding is preferred because it is: (a) Expensive (c) Difficult to prepare Ans: Reusable
		(b) Reusable (d) Non-plastic
3	15	Electroless nickel infiltration adds (a) Corrosion resistance in pores (c) Nitride layer Ans: Corrosion resistance in pores
		(b) Carburized case (d) Decarburized layer
3	16	Decarburization during heat treatment leads to (a) Lower surface hardness (c) No effect Ans: Lower surface hardness
		(b) Higher surface hardness (d) Carbide network at surface
3	17	Which welding process uses non-consumable tungsten electrode? (a) MIG (c) SMAW Ans: TIG
		(b) TIG (d) Submerged arc welding
3	18	Drop forging is mainly used for: (a) Thin sheets (c) Precision parts Ans: Mass production
		(b) Complex shapes (d) Mass production
3	19	Which heat treatment process increases toughness by heating below critical point? (a) Normalizing (c) Carburizing Ans: Tempering
		(b) Tempering (d) Quenching
3	20	Sintering in powder metallurgy improves: (a) Color (c) Density and strength Ans: Density and strength
		(b) Corrosion (d) Weight

U.NO	Q.NO	QUESTIONS
3	21	<p>Powder metallurgy typically aims for</p> <p>(a) Near-net shape (b) Casting risers</p> <p>(c) Arc welding (d) Drop forging</p> <p>Ans:Near-net shape</p>
3	22	<p>Powder metallurgy parts often require</p> <p>(a) Secondary operations like sizing/impregnation (b) Arc welding</p> <p>(c) Hot forging always (d) Carburizing never</p> <p>Ans:Secondary operations like sizing/impregnation</p>
3	23	<p>Martensite start temperature (Ms) is</p> <p>(a) Temperature where martensite begins to form on cooling (b) Start of pearlite</p> <p>(c) Boiling point of oil (d) A1</p> <p>Ans:Temperature where martensite begins to form on cooling</p>
3	24	<p>Nitriding advantage over carburizing is</p> <p>(a) Less distortion (no quench needed) (b) Deeper case for same time</p> <p>(c) Lower fatigue strength (d) More decarburization</p> <p>Ans:Less distortion (no quench needed)</p>
3	25	<p>A sintering aid in PM for WC-Co is</p> <p>(a) Cobalt binder (b) Chromium nitride</p> <p>(c) Sodium chloride (d) Lead</p> <p>Ans:Cobalt binder</p>
3	26	<p>Powder compacts with density gradients are improved by</p> <p>(a) Double-action pressing (b) Lowering pressure</p> <p>(c) Removing lubricant (d) Using coarser powder only</p> <p>Ans:Using coarser powder only</p>
3	27	<p>Hardenability represents</p> <p>(a) Depth to which steel hardens on quenching (b) Maximum attainable hardness</p> <p>(c) Toughness (d) Ductility</p> <p>Ans:Depth to which steel hardens on quenching</p>
3	28	<p>Tempering at too high temperature can cause</p> <p>(a) Softening and over-tempering (b) Increased hardness</p> <p>(c) Martensite reformation (d) No change</p> <p>Ans:Softening and over-tempering</p>
3	29	<p>Bainite forms at</p> <p>(a) Intermediate temperatures between pearlite and martensite (b) Very high temperatures</p> <p>(c) Room temperature only (d) Above Acm</p> <p>Ans:Intermediate temperatures between pearlite and martensite</p>
3	30	<p>Austempering quench medium commonly is</p> <p>(a) Molten salt bath (b) Water</p> <p>(c) Brine (d) Air</p> <p>Ans:Molten salt bath</p>

U.NO	Q NO	QUESTIONS	
3	31	Quenching in oil compared to water gives (a) Slower cooling and less distortion (c) No HAZ	(b) Faster cooling (d) More cracking
		Ans:Slower cooling and less distortion	
3	32	TTT diagrams plot (a) Temperature vs time of transformations (c) Voltage vs current	(b) Stress vs strain (d) Depth vs time
		Ans:Temperature vs time of transformations	
3	33	Reduction method produces powders by (a) Reducing metal oxides (c) Electroplating	(b) Melting and spraying (d) Grinding only
		Ans:Reducing metal oxides	
3	34	Full annealing involves (a) Heating above A3/Acm and slow cooling (c) Rapid cooling from above A1	(b) Heating below A1 then quench (d) No soaking
		Ans:Heating above A3/Acm and slow cooling	
3	35	Normalizing steel results in (a) Refined, uniform pearlitic structure (c) Full annealing softness	(b) Highest hardness (d) Austenite retention
		Ans:Refined, uniform pearlitic structure	
3	36	Isothermal annealing is used to (a) Improve ductility and refine pearlite (c) Create bainite only	(b) Form martensite (d) Harden copper
		Ans:Improve ductility and refine pearlite	
3	37	TIG is unrelated to (a) Powder metallurgy (c) Sintering	(b) Heat treatment (d) Compaction
		Ans:Compaction	
3	38	Typical PM advantage is (a) Near-net shape with minimal scrap (c) Unlimited part size	(b) Always higher density than wrought (d) High ductility
		Ans:Near-net shape with minimal scrap	
3	39	Green strength refers to (a) Strength of compact before sintering (c) Fluidity of melt	(b) Strength after sintering (d) Hardness after heat treatment
		Ans:Strength of compact before sintering	
3	40	Process annealing is used to (a) Remove work hardening in low-carbon steel (c) Precipitation harden Al	(b) Harden tool steel (d) Create martensite
		Ans:Remove work hardening in low-carbon steel	

U.NO	Q NO	QUESTIONS	
3	41	A common lubricant in PM compaction is (a) Zinc stearate (c) Lead oxide Ans:Zinc stearate	(b) Mercury (d) NaCl
3	42	Sizing after sintering is used to (a) Improve dimensional accuracy (c) Remove oxides Ans:Improve dimensional accuracy	(b) Add lubricants (d) Change composition
3	43	Sintering is performed (a) Below melting point to bond particles (c) At room temperature Ans:Below melting point to bond particles	(b) Above melting point (d) Only in vacuum
3	44	Compacting in powder metallurgy aims to (a) Achieve desired density and shape (c) Remove all porosity Ans:Achieve desired density and shape	(b) Melt the powder (d) Create oxide layers
3	45	Electrolytic deposition for powders yields (a) High purity powders (c) Lowest purity Ans:High purity powders	(b) Largest particle size (d) Always brittle powders
3	46	Atomization is a method used to (a) Produce metal powders (c) Harden steels Ans:Produce metal powders	(b) Sinter compacts (d) Coat powders
3	47	Precipitation hardening is typical of (a) Al-Cu alloys (c) Cast iron only Ans:Al-Cu alloys	(b) Plain carbon steels (d) Pure copper
3	48	Infiltration introduces (a) A lower melting metal into pores (c) Ceramics into pores Ans:A lower melting metal into pores	(b) Gases to pores (d) Flakes to strengthen
3	49	Spheroidize annealing produces (a) Globular carbides in ferrite (c) Bainite Ans:Globular carbides in ferrite	(b) Martensite (d) Retained austenite
3	50	A design rule for PM parts is to (a) Avoid sharp changes in section (c) Use long thin walls Ans:Avoid sharp changes in section	(b) Include deep undercuts (d) Vary thickness abruptly

U.NO	Q NO	QUESTIONS
4	1	Spot facing is commonly done using (a) End mill/counterbore (c) Tap Ans:Twist drill only
		(b) Twist drill only (d) Reamer
4	2	Built-up edge in drilling causes (a) Poor finish and size error (c) Lower torque always Ans:Poor finish and size error
		(b) Improved accuracy (d) No effect
4	3	Runout in drilling leads to (a) Oversize holes (c) No change Ans:Undersize holes always
		(b) Undersize holes always (d) Tapered holes smaller
4	4	Cutting speed for drilling is based on (a) Peripheral speed at drill diameter (c) Machine power Ans:Machine power
		(b) Spindle torque (d) Chip load only
4	5	Drill jig provides (a) Accurate location and guidance for drill (c) Lubrication Ans:Coolant only
		(b) Power to the spindle (d) Coolant only
4	6	Tapping creates (a) Internal threads (c) Countersink Ans:External threads
		(b) External threads (d) Counterbore
4	7	Drill sleeves are used when (a) Drill taper is smaller than spindle taper (c) Using chucks Ans:Drill taper larger
		(b) Drill taper larger (d) Using collets
4	8	Boring operation is used to (a) Enlarge and improve accuracy of an existing hole (c) Create threads Ans:Create threads
		(b) Start a new hole (d) Spot face
4	9	Coolant application in drilling is most effective when (a) Delivered to cutting edges and chip gullet (c) Flood on table Ans:Random
		(b) Sprayed on chuck (d) Random
4	10	Coolant through spindle is common in (a) CNC machining centers (c) Hand drills Ans:Hand drills
		(b) Bench drills (d) Shapers

U.NO	Q NO	QUESTIONS
4	11	Spot drill angle compared to standard drill (a) Is larger for stiffness (b) Is smaller (c) Same (d) Irrelevant Ans: Is larger for stiffness
4	12	For tough alloys, recommended cutting speed is (a) Lower than for mild steel (b) Higher (c) Same (d) Irrelevant Ans: Lower than for mild steel
4	13	Pilot holes help to (a) Guide larger drills and reduce thrust (b) Increase burrs (c) Increase runout (d) Reduce accuracy Ans: Guide larger drills and reduce thrust
4	14	Drill bushes in jigs are made of (a) Hardened steel (b) Aluminium (c) Copper (d) Lead Ans: Hardened steel
4	15	Spot facing operation aims to (a) Provide flat seating surface (b) Create threads (c) Drill deep holes (d) Tap holes Ans: Tap holes
4	16	Powder metallurgy is especially suitable for making: (a) Large castings (b) Porous bearings (c) Forged tools (d) Sheet metal parts Ans: Porous bearings
4	17	Carbide tools are preferred because they: (a) Are cheaper (b) Withstand higher temperatures (c) Rust easily (d) Are softer Ans: Withstand higher temperatures
4	18	Cutting fluids are used mainly to: (a) Polish surface (b) Increase tool hardness (c) Reduce heat and friction (d) Change tool shape Ans: Reduce heat and friction
4	19	Spot facing is done to: (a) Polish the hole (b) Increase hardness (c) Create threads (d) Produce flat surface for seating Ans: Produce flat surface for seating
4	20	A radial drilling machine is used for: (a) Tapping only (b) Small holes (c) Thread cutting (d) Large workpieces Ans: Large workpieces

U.NO	Q NO	QUESTIONS	
4	21	Orthogonal cutting differs from oblique cutting in: (a) Chip thickness (c) Tool geometry Ans:Tool geometry	(b) Machine used (d) Number of cutting edges
4	22	Carbide tools are preferred because they: (a) Rust easily (c) Are softer Ans:Withstand higher temperatures	(b) Are cheaper (d) Withstand higher temperatures
4	23	Spot drilling is done to (a) Create accurate starting point (c) Tap hole Ans:Finish hole	(b) Finish hole (d) Bore large diameters
4	24	Tool wear monitoring in drilling tracks (a) Torque/thrust increase (c) Coolant color Ans:Machine color	(b) Spindle temperature only (d) Machine color
4	25	Feeds in drilling are specified in (a) mm/rev (c) rev/min only Ans:mm/min only	(b) mm/min only (d) N·m
4	26	Bench drilling machine is (a) Small drill on a bench (c) CNC machining center Ans:Portable hand drill only	(b) Radial drill (d) Portable hand drill only
4	27	Gang drilling machine has (a) Multiple drills on a common table (c) CNC axes only Ans:Rotary table only	(b) Only one spindle (d) Rotary table only
4	28	Drills most commonly used are (a) Twist drills (c) Gun drills only Ans:Trepan drills only	(b) Flat spade drills only (d) Trepan drills only
4	29	Oblique cutting has chip flow (a) At an angle to cutting edge (c) Not defined Ans:Normal to cutting edge	(b) Normal to cutting edge (d) Parallel to velocity
4	30	Specific cutting energy generally (a) Decreases with increasing feed (c) Unaffected by chip load Ans:Increases with depth	(b) Increases with depth (d) Independent of material

U.NO	Q NO	QUESTIONS	
4	31	Minimum chip thickness concept is important in (a) Micro-machining (c) Manual filing Ans:Manual filing	(b) Heavy roughing (d) Forging
4	32	High speed steel is best for (a) Interrupted cuts and toughness (c) Abrasive composites Ans:Only drilling wood	(b) Very high speed dry cuts always (d) Only drilling wood
4	33	Cemented carbides are (a) WC particles bonded with Co (c) Ceramic oxides only Ans:HSS with Coating	(b) HSS with Coating (d) Cermets only
4	34	Point angle of a standard twist drill (for steel) is (a) 118° (approx.) (c) 45° Ans:30°	(b) 30° (d) 170°
4	35	Single point cutting tool nomenclature includes (a) Back rake, side rake, relief angles (c) Point angle only Ans:Helix angle only	(b) Helix angle only (d) No rake
4	36	Cutting fluids primarily (a) Cool and lubricate the cutting zone (c) Reduce spindle speed only Ans:Change tool geometry	(b) Increase hardness of tool (d) Change tool geometry
4	37	Crater wear occurs on (a) Rake face due to chip flow (c) Tool shank Ans:Flank face	(b) Flank face (d) Work holder
4	38	Tool life is commonly related to cutting speed by (a) Taylor's equation (c) Bernoulli's principle Ans:Taylor's equation	(b) Hooke's law (d) Fourier law
4	39	Positive rake angle generally (a) Reduces cutting force (c) Eliminates chip flow Ans:Increases tool wear only	(b) Increases built-up edge always (d) Increases tool wear only
4	40	Shear plane angle affects (a) Chip thickness and cutting force (c) Coolant type Ans:Chip thickness and cutting force	(b) Tool material only (d) Machine color

U.NO	Q.NO	QUESTIONS
4	41	Orthogonal cutting assumes (a) Cutting edge perpendicular to cutting velocity (c) Zero rake always Ans:Cutting edge perpendicular to cutting velocity
		(b) Oblique angle $< 0^\circ$ (d) No chip formation
4	42	Built-up edge is promoted by (a) Low cutting speed and high friction (c) Sharp tools and coatings Ans:Low cutting speed and high friction
		(b) High cutting speed with coolant (d) Negative rake only
4	43	Chisel edge of a drill (a) Does not cut; extrudes material (c) Guides the drill Ans:Is the main cutting lip
		(b) Is the main cutting lip (d) Holds coolant
4	44	Flank wear occurs on (a) Relief (flank) face of tool (c) Nose radius Ans:Relief (flank) face of tool
		(b) Rake face (d) Shank
4	45	Reaming operation is for (a) Finishing and sizing a hole (c) Creating threads Ans:Starting a hole
		(b) Starting a hole (d) Spot facing only
4	46	Drill chucks are held in spindles via (a) Taper (Morse/Jacobs) (c) Keys only Ans:Taper (Morse/Jacobs)
		(b) Threaded rods (d) Bolted flanges
4	47	Radial drilling machine is suited for (a) Large, heavy jobs (c) Wire EDM Ans:Gear shaping only
		(b) Tiny watch parts (d) Gear shaping only
4	48	Multi-spindle drills are used for (a) Drilling many holes simultaneously (c) Tapping only Ans:Drilling many holes simultaneously
		(b) Gun drilling only (d) Reaming only
4	49	Drill margin refers to (a) Narrow land along outer edges (c) Chisel edge Ans:Narrow land along outer edges
		(b) Web thickness (d) Helix angle
4	50	For brittle materials, the recommended drill point angle is (a) Larger to reduce chipping (c) Unchanged Ans:Larger to reduce chipping
		(b) Very small (d) None

U.NO	Q NO	QUESTIONS
5	1	<p>Angle grinder is commonly used for</p> <p>(a) Grinding and cutting with discs (b) Drilling holes (c) Turning (d) Planing</p> <p>Ans:Grinding and cutting with discs</p>
5	2	<p>Screwdrivers (power) are used for</p> <p>(a) Driving screws quickly (b) Knurling (c) Turning (d) Grinding</p> <p>Ans:Driving screws quickly</p>
5	3	<p>Tool post types include</p> <p>(a) Single, four-way, quick-change (b) Only single-type (c) Only four-way (d) Only quick-change</p> <p>Ans:Single, four-way, quick-change</p>
5	4	<p>Depth of cut, feed and speed together define</p> <p>(a) Material removal rate (b) Thread pitch (c) Tool hardness (d) Lead angle</p> <p>Ans:Material removal rate</p>
5	5	<p>Automatic cross feed enables</p> <p>(a) Uniform facing and turning (b) Manual hand feed only (c) Threading only (d) Taper only</p> <p>Ans:Uniform facing and turning</p>
5	6	<p>Turning speed (rpm) is selected from</p> <p>(a) Cutting speed and work diameter (b) Feed only (c) Depth only (d) Tool nose radius only</p> <p>Ans:Cutting speed and work diameter</p>
5	7	<p>Cutting fluid in turning helps to</p> <p>(a) Cool and lubricate (b) Increase runout (c) Loosen chuck (d) Clean coolant tank only</p> <p>Ans:Cool and lubricate</p>
5	8	<p>Tool overhang should be</p> <p>(a) As small as possible (b) As large as possible (c) Equal to work length (d) Irrelevant</p> <p>Ans:As small as possible</p>
5	9	<p>Work between centers uses</p> <p>(a) Lathe centers and a drive (b) Only chuck (c) Only collet (d) Only faceplate</p> <p>Ans:Lathe centers and a drive</p>
5	10	<p>Cartridge type live center contains</p> <p>(a) Bearings to rotate with work (b) Fixed dead point (c) Magnet (d) Gear</p> <p>Ans:Bearings to rotate with work</p>

U.NO	Q NO	QUESTIONS
5	11	Turning hard materials often uses (a) CBN or ceramic tools (c) Wood tools Ans:CBN or ceramic tools
		(b) HSS always (d) Plastic inserts
5	12	Knurling feed is (a) High to emboss pattern (c) Same as turning Ans:Very low
		(b) Very low (d) Zero
5	13	Short work held in chuck must (a) Project minimum length for stiffness (c) Be unsupported Ans:Project minimum length for stiffness
		(b) Project maximum length (d) Be hammered in
5	14	Power tool 'blower' mainly serves to (a) Clear chips/dust (c) Turn work Ans:Clear chips/dust
		(b) Cut threads (d) Grind
5	15	Heat gun among power tools is used for (a) Paint stripping/shrink fit (c) Mixing concrete Ans:Paint stripping/shrink fit
		(b) Cutting steel (d) Measuring temperature
5	16	Lathe lead screw pitch determines (a) Thread pitches possible (c) Tool nose radius Ans:Thread pitches possible
		(b) Spindle speed (d) Chuck size
5	17	Tool wear on lathes is minimized by (a) Correct speed, feed, coolant (c) Dull tools Ans:Correct speed, feed, coolant
		(b) Excess speed (d) Dry cut always
5	18	The apron in a lathe is part of the: (a) Tailstock (c) Headstock Ans:Carriage
		(b) Bed (d) Carriage
5	19	Travelling steady supports (a) Work near the cutting point (c) Toolpost Ans:Work near the cutting point
		(b) Tailstock (d) Chuck
5	20	Depth of cut in turning is (a) Half the reduction in diameter (c) Twice reduction Ans:Half the reduction in diameter
		(b) Equal to reduction in diameter (d) Independent

U.NO	Q NO	QUESTIONS
5	21	Thread cutting on a lathe uses (a) Leadscrew synchronized with spindle (b) Random feed (c) Only cross feed (d) Tailstock feed Ans:Leadscrew synchronized with spindle
5	22	Taper turning by offset method uses (a) Tailstock set-over (b) Form tool (c) Taper attachment only (d) Compound rest only Ans:Tailstock set-over
5	23	Knurling operation produces (a) Regular textured pattern (b) Internal thread (c) External taper (d) Flat face Ans:Regular textured pattern
5	24	Types of centres include (a) Live, dead and half centres (b) Only dead centre (c) Only live centre (d) Only revolving centre Ans:Live, dead and half centres
5	25	Catch plate and carrier are used for (a) Driving work between centers (b) Holding drills (c) Holding tools (d) Clamping fixtures Ans:Driving work between centers
5	26	Faceplate is used to (a) Hold irregular workpieces (b) Hold twist drills (c) Hold reamers (d) Grip small bar Ans:Hold irregular workpieces
5	27	Four-jaw chuck is preferred for (a) Eccentric or square jobs (b) Round bars only (c) Thin sheets (d) Wood only Ans:Eccentric or square jobs
5	28	Three-jaw chuck is (a) Self-centering (b) Independent jaws (c) Not used on lathes (d) Magnetic Ans:Self-centering
5	29	Tailstock supports (a) Work with centers and drills (b) Only tool post (c) Gearbox (d) Chuck Ans:Work with centers and drills
5	30	Compound rest is useful for (a) Taper turning and tool setting (b) Facing only (c) Drilling (d) Boring bar support only Ans:Taper turning and tool setting

U.NO	Q NO	QUESTIONS
5	31	<p>Cross slide provides</p> <p>(a) Transverse feed (b) Longitudinal feed (c) Compound angle only (d) No feed</p> <p>Ans:Transverse feed</p>
5	32	<p>Apron mechanism controls</p> <p>(a) Carriage movements and feed (b) Spindle speed (c) Chuck jaws (d) Tailstock barrel</p> <p>Ans:Carriage movements and feed</p>
5	33	<p>Quick-change gear box is used for</p> <p>(a) Rapid selection of feeds and threads (b) Changing spindle bearings (c) Tailstock offset (d) Coolant control</p> <p>Ans:Rapid selection of feeds and threads</p>
5	34	<p>Back-gearred headstock provides</p> <p>(a) Low speeds with high torque (b) High speeds only (c) Only threading (d) No change in torque</p> <p>Ans:Low speeds with high torque</p>
5	35	<p>Headstock houses</p> <p>(a) Spindle and gear train (b) Tailstock barrel only (c) Apron (d) Leadscrew</p> <p>Ans:Spindle and gear train</p>
5	36	<p>A centre lathe primarily performs</p> <p>(a) Turning operations (b) Milling (c) Planing (d) Grinding only</p> <p>Ans:Turning operations</p>
5	37	<p>Facing operation produces</p> <p>(a) Flat surface at end of work (b) Cylindrical surface (c) Thread (d) Taper</p> <p>Ans:Flat surface at end of work</p>
5	38	<p>CNC lathes differ by</p> <p>(a) Programmable control of motions (b) Manual gears only (c) No spindle (d) No tailstock possible</p> <p>Ans:Programmable control of motions</p>
5	39	<p>Boring on a lathe</p> <p>(a) Enlarges an existing hole (b) Drills a new hole (c) Faces a surface (d) Knurls</p> <p>Ans:Enlarges an existing hole</p>
5	40	<p>Feed in turning is expressed in</p> <p>(a) mm/rev (b) mm/min only (c) rev/min (d) N·m</p> <p>Ans:mm/rev</p>

U.NO	Q NO	QUESTIONS	
5	41	Steady rest is used to (a) Support long workpieces (c) Drive the work Ans:Support long workpieces	(b) Hold tools (d) Change speed
5	42	Taper turning using compound rest is suitable for (a) Short, steep tapers (c) Threads Ans:Short, steep tapers	(b) Long gentle tapers (d) Knurls
5	43	Chamfering on a lathe produces (a) Beveled edge (c) Internal thread Ans:Beveled edge	(b) Knurled surface (d) Concave radius
5	44	Lathe centers are usually made of (a) Hardened steel (c) Brass Ans:Hardened steel	(b) Aluminium (d) Lead
5	45	Spindle nose carries (a) Chuck/faceplate (c) Leadscrew Ans:Chuck/faceplate	(b) Tailstock (d) Apron
5	46	Mandrel is used to (a) Hold hollow work for machining (c) Hold centers Ans:Hold hollow work for machining	(b) Hold drills (d) Measure taper
5	47	Work holding device to hold very small diameter stock (a) Collet chuck (c) Four-jaw chuck Ans:Collet chuck	(b) Faceplate (d) Drive plate
5	48	Carriage consists of (a) Saddle, cross-slide, compound, apron (c) Base and column Ans:Saddle, cross-slide, compound, apron	(b) Headstock and tailstock (d) Slideways only
5	49	Quick-change tool post enables (a) Rapid tool swapping (c) Tailstock movement Ans:Rapid tool swapping	(b) Reverse spindle (d) Headstock change
5	50	Chuck runout is checked by (a) Dial indicator (c) Feeler gauge Ans:Dial indicator	(b) Vernier caliper (d) Micrometer screw only

SHORT ANSWER QUESTIONS

3 marks

PART B UNIT I

- 1 Describe the step-by-step procedure of sand casting with a neat sketch.
- 2 Describe the various types of patterns based on their construction and material.
- 3 Discuss the properties and selection criteria of molding sand.
- 4 Discuss the principles and applications of die casting.
- 5 Describe the function of various casting allowances.
- 6 Describe the working of the investment casting process.
- 7 Discuss the common casting defects, their causes, and remedies.
- 8 Describe the principles of shell molding.
- 9 Describe the purpose of a gating system and its components.
- 10 Differentiate between cold chamber and hot chamber die casting.

PART B UNIT II

- 1 Describe the principles of hot working and its effects on the properties of a metal.
- 2 Describe the advantages and disadvantages of hot working and cold working.
- 3 Describe the hot rolling process for producing sheets or plates.
- 4 Discuss the cold drawing process for manufacturing wires or rods.
- 5 Describe the various types of extrusion processes.
- 6 Discuss forging and its different types.
- 7 Discuss the effects of cold working on the mechanical properties of a material.
- 8 Describe the working principle of the sheet metal bending process.
- 9 Discuss the rolling process and its applications.
- 10 Compare hot working and cold working processes.

PART B UNIT III

- 1 Discuss the powder metallurgy process with a neat flow chart.
- 2 Describe the various methods of manufacturing metal powders.
- 3 Discuss the advantages and limitations of powder metallurgy.
- 4 Describe the purpose and working of annealing and normalizing processes.
- 5 Describe the hardening and tempering heat treatment processes.

- 6 Describe case hardening and its different methods, such as carburizing and nitriding.
- 7 Discuss the applications of various heat treatment processes.
- 8 Enumerate the role of a sintering furnace in powder metallurgy.
- 9 Describe the different types of quenching media.
- 10 Discuss the T-T-T diagram and its importance in heat treatment.

PART B UNIT IV

- 1 Describe the construction and working principle of a radial drilling machine.
- 2 Enumerate the various types of tool materials used in machining with their properties.
- 3 Describe the different types of drilling operations with neat sketches.
- 4 Discuss the working of a sensitive drilling machine and its applications.
- 5 Discuss the properties of cutting fluids and their functions.
- 6 Discuss the different tool holding devices for drilling machines.
- 7 Describe the tapping operation and the types of taps used.
- 8 Discuss the process of boring and the tools used.
- 9 Discuss the advantages and disadvantages of carbide tools.
- 10 Write about the feed and speed in a drilling operation.

PART B UNIT V

- 1 Discuss the working principle of a lathe machine with a neat diagram.
- 2 Describe the various lathe operations with suitable sketches.
- 3 Write about the mechanism for taper turning on a lathe.
- 4 Discuss the different types of lathe chucks and their applications.
- 5 Describe the working of a lead screw and its importance in thread cutting.
- 6 Discuss the compound rest method for taper turning.
- 7 Discuss the various power tools used in manufacturing and their applications.
- 8 Describe the function of a steady rest and follower rest.
- 9 Enumerate the procedure for facing a job on a lathe.
- 10 What is a quick change gear box and how does it work?

EXPLANATORY QUESTIONS

10 marks

PART C UNIT I

- 1 What is a pattern? Explain the types of patterns used in the foundry.
- 2 Explain pattern allowances with simple examples.
- 3 What is moulding sand? Explain its types and properties.
- 4 Explain the CO₂ core making process in simple steps.
- 5 What are casting defects? Explain any five defects with causes and remedies.

PART C UNIT II

- 1 What is arc welding? Explain arc welding equipment..
- 2 Explain MIG welding and TIG welding briefly.
- 3 What is gas welding? Explain oxy-acetylene welding.
- 4 Explain the types of flames used in gas welding.
- 5 What are welding defects? Explain their causes and remedies.

PART C UNIT III

- 1 What is forging? Explain hot working and its advantages.
- 2 Explain smith forging, drop forging and press forging.
- 3 Explain the rolling process with a simple sketch.
- 4 Explain mechanical press and hydraulic press.
- 5 Explain press working operations like bending and drawing.

PART C UNIT IV

- 1 What is powder metallurgy? Explain its basic steps.
- 2 Explain methods of manufacturing metal powders.
- 3 Explain the sintering process in powder metallurgy.
- 4 Explain the Iron–Carbon equilibrium diagram briefly.
- 5 Explain annealing, normalizing and hardening processes.

PART C UNIT V

- 1 Explain work holding devices used in the lathe.
- 2 Explain chucks and centres with their uses.
- 3 Explain tool holding devices used in machines.
- 4 What are power tools? Explain any five power tools.
- 5 Explain hand drill, angle grinder and impact wrench.